


Central bunks changed with closing bunk Port and closets SB








Rewired all electrics and new electronics







New Andersen Winches



all batteries Leak from water collection on cockpit roof









